

Reparatursatz Kugelrückschlagventil ULH 250-K (Art.-Nr. 12141291)


X: Reparatursatz Steuerkolben (Art.-Nr. 12141291X (nur X-Satz))
bestehend aus je 1 x Pos. 16, Pos. 17, Pos. 20, Pos. 28

Y: Reparatursatz Rückschlagventil
bestehend aus je 1 x Pos. 6, Pos. 7, Pos. 8, Pos. 9, Pos. 11, Pos. 12


Z: Reparatursatz Bypass
bestehend aus je 1 x Pos. 6, Pos. 7, Pos. 8, Pos. 9, Pos. 10, Pos. 11.1

MH Manfred Hoffmann

Alte Ziegelei 3 • 51491 Overath
Tel.: (02204) 98721-0 • Fax: (02204) 98721-29
eMail: info@hoffmann-carwash.de
Web: www.hoffmann-carwash.de



Montage Pos. 16



Montage Pos. 20

